



client SPH industry Printing & Packaging location Jurong, Singapore date 1999 - 2008

**TOTAL INSALLATION AREA**

25,000 m<sup>2</sup>

**PROBLEM FACED BY CLIENT**

Over the years, the existing concrete in the production areas weakened due to daily mechanical and impact abrasion by forklift movement and heavy machineries, which led to the affected area being dusty as the surface of the concrete loosens.

**CLIENT'S REQUIREMENT**

Hence, the flooring specification called for a dust-free and easy to maintain flooring system which would improve the aesthetics of the production area and guard against potential health hazards caused by concrete dust.

**SOLUTION OFFERED**

**Polygard™ SLT 1090** | 1mm thick solventless epoxy self-leveling system with smooth finish (PU topping)

In 1999, SLT 1090 was applied on the Mail RM / Reel Preparation area. Three years later, the system was also applied onto the new extension. To date, 11 years after installation, the floor is still in good condition and continues to provide protection and meet customer's expectations.

---

For more information, contact **Polymer International** on tel (+65) 6749 3113, email [sales@polymer-international.com](mailto:sales@polymer-international.com) or visit [www.polymer-international.com](http://www.polymer-international.com).